




A PROFIL PRZYŚCIENNY




F ZAWIAS




B PROFIL PRZYŚCIENNY





G UCHWYT




C UCHWYT




I ZAKOŃCZENIE PROGU



D WSPORNIK



J PROFIL - WYMIARY



E WSPORNIK




TABELA ROZMIARÓW:

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1	X2
K-0619	1/L	100x70x195	czyste 6mm	99,5-101	69,5-71	21	71	195	98,2-99,7	68,2-69,7
K-0620	1/P	100x70x195	czyste 6mm	99,5-101	69,5-71	21	71	195	98,2-99,7	68,2-69,7
K-0376	1/L	100x80x195	czyste 6mm	99,5-101	79,5-81	21	71	195	98,2-99,7	78,2-79,7
K-0377	1/P	100x80x195	czyste 6mm	99,5-101	79,5-81	21	71	195	98,2-99,7	78,2-79,7
K-0378	1/L	100x90x195	czyste 6mm	99,5-101	89,5-91	21	71	195	98,2-99,7	88,2-89,7
K-0379	1/P	100x90x195	czyste 6mm	99,5-101	89,5-91	21	71	195	98,2-99,7	88,2-89,7
K-0380	1/L	100x100x195	czyste 6mm	99,5-101	99,5-101	21	71	195	98,2-99,7	98,2-99,7
K-0381	1/P	100x100x195	czyste 6mm	99,5-101	99,5-101	21	71	195	98,2-99,7	98,2-99,7
K-0621	1/L	100x110x195	czyste 6mm	99,5-101	109,5-111	21	71	195	98,2-99,7	108,2-109,7
K-0622	1/P	100x110x195	czyste 6mm	99,5-101	109,5-111	21	71	195	98,2-99,7	108,2-109,7
K-0623	1/L	100x120x195	czyste 6mm	99,5-101	119,5-121	21	71	195	98,2-99,7	118,2-119,7
K-0624	1/P	100x120x195	czyste 6mm	99,5-101	119,5-121	21	71	195	98,2-99,7	118,2-119,7
K-0625	1/L	110x70x195	czyste 6mm	109,5-111	69,5-71	31	71	195	108,2-109,7	68,2-69,7
K-0626	1/P	110x70x195	czyste 6mm	109,5-111	69,5-71	31	71	195	108,2-109,7	68,2-69,7
K-0382	1/L	110x80x195	czyste 6mm	109,5-111	79,5-81	31	71	195	108,2-109,7	78,2-79,7
K-0383	1/P	110x80x195	czyste 6mm	109,5-111	79,5-81	31	71	195	108,2-109,7	78,2-79,7
K-0384	1/L	110x90x195	czyste 6mm	109,5-111	89,5-91	31	71	195	108,2-109,7	88,2-89,7
K-0385	1/P	110x90x195	czyste 6mm	109,5-111	89,5-91	31	71	195	108,2-109,7	88,2-89,7
K-0386	1/L	110x100x195	czyste 6mm	109,5-111	99,5-101	31	71	195	108,2-109,7	98,2-99,7
K-0387	1/P	110x100x195	czyste 6mm	109,5-111	99,5-101	31	71	195	108,2-109,7	98,2-99,7
K-0627	1/L	110x110x195	czyste 6mm	109,5-111	109,5-111	31	71	195	108,2-109,7	108,2-109,7
K-0628	1/P	110x110x195	czyste 6mm	109,5-111	109,5-111	31	71	195	108,2-109,7	108,2-109,7
K-0629	1/L	110x120x195	czyste 6mm	109,5-111	119,5-121	31	71	195	108,2-109,7	118,2-119,7
K-0630	1/P	110x120x195	czyste 6mm	109,5-111	119,5-121	31	71	195	108,2-109,7	118,2-119,7